#### explanatory note —

The seat drop value described in the compatibility table is primarily a value relative to the original-equipment seat. It is measured by mounting a Recaro or Bride full bucket seat at the lowest position possible without the seat bottom interfering with the seat rail or vehicle floor. Differences may arise due to the position of the seat to be mounted (the position of the bolt holes), the thickness and shape of the bottom of the seat, and seat settling due to aging of the original-equipment seat.

Note: If the original-equipment seat incorporates a height adjustment function, this value is relative to the lowest position.

Note: As a general rule, driver's seat data (passenger seats have different values depending on the presence or absence of height adjustment function)

# **ENGLAND(GB)**

### **ASTON MARTIN**

| Model Name | Model Code | Seat Drop | Туре | Right Part No. | Left Part No. | Side SRS | Remarks  |
|------------|------------|-----------|------|----------------|---------------|----------|--|
| V8 Vantage | -          | -20mm     | S1   | IAN1020S01R    | IAN1020S01L   | NPC001   | '05~ 3rd generation Offset toward door side is 12 mm. Only driver's seats with seat cushion widths of 510 mm or more will interfere. |

#### **JAGUAR**

| Model Name | Model Code                 | Seat Drop | Type | Right Part No. | Left Part No. | Side SRS | Remarks  |
|------------|----------------------------|-----------|------|----------------|---------------|----------|--|
| F-PACE     | DC2NA,DC2XB<br>DC2NA,DC3VA | No data   | S6   | IJR1080S06R    | IJR1080S06L   | NPC001   |  |
| JAGUAR Mk2 | -                          | No data   | S1   | IJR1020S01R    | IJR1020S01L   | -        |  |
| S TYPE     | J01                        | -10mm     | S6   | IJR1070S06R    | IJR1070S06L   | NPC002   | Offset toward door side is 20 mm.  |
| XF         | J05                        | -20mm     | S1   | IJR1030S01R    | IJR1030S01L   | NPC001   | Offset toward door side is 10 mm.  |
| XJ         | JL                         | -15mm     | S4   | IJR1060S04R    | IJR1060S04L   | -        |  |
| хэ         | J71,72,73,80,81            | -20mm     | S4   | IJR1040S16R    | IJR1040S16L   | NPC001   | Offset toward door side is 7 mm.  Seat drop is from Model Executive4.2L(J72SB) specifications. |
| XJS        | JED,JD                     | -15mm     | S1   | IJR1050S01R    | IJR1050S01L   | -        |  |

## LAND ROVER

| Model Name  | Model Code  | Seat Drop | Туре | Right Part No. | Left Part No. | Side SRS | Remarks  |
|-------------|-------------|-----------|------|----------------|---------------|----------|--|
| DISCOVERY   | LJ22D,LJ16L | -20mm     | S1   | ILR1050S01R    | ILR1050S01L   | -        | <sup>'</sup> 91~'95  |
| DISCOVERY   | LJR,LJL     | -10mm     | S4   | ILR1040S04R    | ILR1040S04L   | -        | ′94~′99  |
| DISCOVERY   | LA40A,LA44  | -20mm     | S4   | ILR1060S04R    | ILR1060S04L   | NPC002   | Electronic devices need to be relocated. Use genuine base.   |
| DEFENDER    | LD25,LD30   | +10mm     | S6   | ILR1090S06R    | ILR1090S06L   | -        | Series 90, Series 110 (′50∼)   |
| DEFENDER    | LD25,LD30   | ±Omm      | S1   | ILR1090S01R    | ILR1090S01L   | -        | super low model. Series 90, Series 110 (′50∼)  |
| DEFENDER 90 | LE62        | -20mm     | S36  | ILR1110S36R    | ILR1110S36L   | NPC002   | $^{\prime}$ 19/11 $\sim$ Offset toward door side is 5 mm. Electronic devices need to be relocated. |

| _                 | _           |           |      | •              |               |          |   |  |  |  |
|-------------------|-------------|-----------|------|----------------|---------------|----------|---|--|--|--|
| DEFENDER 90       | LE62        | -20mm     | LS9  | ILR1110S09R    | ILR1110S09L   | NPC002   | '19/11~  Offset toward door side is 5 mm.  Electronic devices need to be relocated.                       |  |  |  |
| DEFENDER 110      | LE72        | -20mm     | S36  | ILR1120S36R    | ILR1120S36L   | NPC002   | '19/11~  Offset toward door side is 5 mm.  Electronic devices need to be relocated.                       |  |  |  |
| DEFENDER 110      | LE72        | -20mm     | LS9  | ILR1120S09R    | ILR1120S09L   | NPC002   | '19/11~  Offset toward door side is 5 mm.  Electronic devices need to be relocated.                       |  |  |  |
| FREELANDER        | LN25        | -10mm     | S16  | ILR1010S16R    | ILR1010S16L   | -        |   |  |  |  |
| RANGE ROVER       | LH36,38,40D | No data   | S4   | ILR1020S04R    | ILR1020S04L   | -        |   |  |  |  |
| RANGE ROVER       | LP42D       | -20mm     | S1   | ILR1030S01R    | ILR1030S01L   | -        | Designed exclusively for Model 4.0,4.0S specification.  Electric seats (4.0SE,4.6SE) cannot be installed. |  |  |  |
| RANGE ROVER VELAR | LY2,LY3     | -10mm     | S6   | ILR1100S06R    | ILR1100S06L   | NPC002   | Electronic devices need to be relocated. (specialty garage recommended for installation).                 |  |  |  |
| RANGE ROVER VELAR | LY2,LY3     | ±Omm      | LS9  | ILR1100S09R    | ILR1100S09L   |          | Electronic devices need to be relocated. (specialty garage recommended for installation).                 |  |  |  |
|                   |             |           |      |                | LO            | TUS      |   |  |  |  |
| Model Name        | Model Code  | Seat Drop | Type | Right Part No. |               | Side SRS | Remarks   |  |  |  |
| EVORA             | -           | No data   | SSD  | ILS1010SSDR    | ILS1010SSDL   | -        |   |  |  |  |
| ROVER             |             |           |      |                |               |          |   |  |  |  |
| Model Name        | Model Code  | Seat Drop | Type | Right Part No. | Left Part No. | Side SRS | Remarks   |  |  |  |
| MGF               | RD18K       | -10mm     | S1   |                | IMG1010S01L   | -        | Interferes with shoulder width exceeding 550 mm.  |  |  |  |
| MG MIDGET         | -           | No data   | S6   | IMG1020S06R    | IMG1020S06L   | -        | '61∼'79   |  |  |  |
| MINI              | 99X,XN12A   | -10mm     | S1   | IRR1040S01R    | IRR1040S01L   | -        |   |  |  |  |
| MINI              | 99X,XN12A   | No data   | S1   | IRR1050S01R    | IRR1050S01L   | -        | Superlow model. Securing the rear requires drilling through the floor. Be aware of the battery cable.     |  |  |  |