— explanatory note —

The seat drop value described in the compatibility table is primarily a value relative to the original-equipment seat. It is measured by mounting a Recaro or Bride full bucket seat at the lowest position possible without the seat bottom interfering with the seat rail or vehicle floor. Differences may arise due to the position of the seat to be mounted (the position of the bolt holes), the thickness and shape of the bottom of the seat, and seat settling due to aging of the original-equipment seat.

Note: If the original-equipment seat incorporates a height adjustment function, this value is relative to the lowest position.

Note: As a general rule, driver's seat data (passenger seats have different values depending on the presence or absence of height adjustment function)

MITSUBISHI

| Model Name | Model Code | Seat Drop | Type | Right Part No. | | | Remarks |
|-----------------|-----------------------------|-----------|------|----------------|-------------|--------|---|
| AIRTREK | CU2W,CU4W | -20mm | S4 | | DMI1120S04L | | Offset toward door side is 5 mm. |
| CANTER | FE437F | No data | S1 | DMI1580S01R | - | - | Mounting dimensions required. 5generation |
| CANTER | FE50EB | No data | S1 | DMI1610S01R | - | - | Mounting dimensions required. 6generation |
| CANTER | FE50EB | No data | S1 | - | DMI1620S01L | - | Mounting dimensions required. 6generation Adapter only (no slide rail). Seats with a convex bottom (such as AM19) are not compatible. Seat rail conversion adapter cannot be installed. |
| CANTER WIDECAB | FE638EV | +10mm | S1 | DMI1550S01R | - | - | Mounting dimensions required. 6generation,wide Offset toward door side is 12 mm. |
| CANTER | FE71D,FG73DC | No data | S1 | DMI1560S01R | - | - | Mounting dimensions required. 7generation |
| CANTER WIDECAB | FEB50 | -20mm | S6 | DMI1660S06R | - | - | Mounting dimensions required. 9generation |
| CANTER GUTS | TZ2F24 | No data | S4 | DMI1570S04R | - | - | Mounting dimensions required. |
| CHALLENGER | K94W~K97W,K99W | -20mm | S4 | DMI1230S04R | DMI1230S04L | - | $^\prime 96/06 \sim ^\prime 99/05$ The K99W passenger seat is compatible with 99/06 and later vehicles. Not compatible with full-time 4WD models with center differential. |
| CHALLENGER | K99W | -15mm | S4 | DMI1231S04R | DMI1250S04L | - | $^{\prime}$ 99/06 \sim Car with full-time 4WD with center differential. |
| CHARIOT | N30W,N40W | -20mm | S4 | DMI1200S04R | DMI1200S04L | - | |
| CHARIOT GRANDIS | N84W,N86W,N94W,N96W | -20mm | S4 | DMI1210S04R | DMI1210S04L | NPC001 | |
| COLT | Z20A~Z28A Z23W,Z24W,Z27W | ±Omm | S6 | DMI1180S06R | DMI1180S06L | NPC001 | Offset toward door side is 5 mm. |
| DELICA D:2 | MB15S | -30mm | S36 | DMI1300S36R | | NPC001 | Offset toward console side is 25 mm. Interferes with shoulder width exceeding 615 mm. |
| DELICA D:2 | MB36S,MB46S | -10mm | S36 | DMI1310S36R | | NPC001 | |
| DELICA D:2 | MB37S | -20mm | S36 | DMI1720S36R | DMI1720S36L | NPC001 | Passenger seat is equipped with a surface pressure sensor for the seat belt warning lamp. |
| DELICA D:3 | ВМ20 | -10mm | S1 | DMI1690S01R | DMI1690S01L | - | Used as a pedestal Common to NV200(M20). The amount of down is NV200 (M20) data. |

| DELICA D:5 | CV5W,CV1W | -30mm | S 36 | DMI1290S36R | DMI1290S36L | - | No side airbag, as curtain airbag is installed. For vehicles after minor change ('19 .11 \sim), the error warning light of the airbag will light up unless the blue coupler itself under the genuine seat is relocated. |
|------------------------|----------------------------------|-------|-------------|-------------|-------------|--------|--|
| DELICA MINI | B34A,B35A,B37A,B38A | -20mm | S6 | DMI1641S06R | DMI1641S06L | NPC001 | Common to 2WD,4WD and EK SPACE(B3#W). Relocation of passenger seat pressure sensor is required. Use genuine base. |
| DELICA MINI | B34A,B35A,B37A,B38A | -20mm | LS9 | DMI1641S09R | DMI1641S09L | NPC001 | Common to 2WD,4WD and EK SPACE(B3#W). Relocation of passenger seat pressure sensor is required. Use genuine base. |
| DELICA SPACE GEAR | PF,PE,PD,PC,PB | -15mm | S4 | DMI1220S04R | DMI1220S04L | - | |
| DIAMANTE | F11~F27 | -10mm | S4 | DMI1260S04R | DMI1260S04L | - | |
| DIAMANTE | F30,F40 | -10mm | S4 | DMI1270S04R | DMI1270S04L | - | |
| DINGO,DION | CQ,CR | -20mm | S4 | DMI1280S04R | DMI1280S04L | - | |
| ECLIPSE | D32A | -10mm | S1 | DMI1130S01R | DMI1130S01L | - | Spider (D53A) cannot be installed. |
| ECLIPSE CROSS | GK1W | -20mm | S36 | DMI1150S36R | DMI1150S36L | NPC001 | Passenger seat is equipped with a surface pressure sensor for the seat belt warning lamp. |
| ECLIPSE CROSS PHEV | GL3W | -20mm | S36 | DMI1650S36R | DMI1650S36L | NPC002 | Passenger seat is equipped with a surface pressure sensor for the seat belt warning lamp. |
| EK SPACE | B11A | -20mm | S36 | DMI1030S36R | DMI1030S36L | NPC001 | Common to DAYZ ROOX(B21A). |
| EK SPACE EK X-SPACE | B34A,B35A,B37A,B38A | -20mm | S6 | DMI1640S06R | DMI1640S06L | NPC001 | Common to 2WD,4WD and ROOX(B4#W). Relocation of passenger seat pressure sensor is required. Use genuine base. |
| EK SPACE EK X-SPACE | B34A,B35A,B37A,B38A | -20mm | LS9 | DMI1640S09R | DMI1640S09L | NPC001 | Common to 2WD,4WD and ROOX(B4#W). Relocation of passenger seat pressure sensor is required. Use genuine base. |
| EK WAGON | H81W,H82W | -20mm | S4 | DMI1010S04R | DMI1010S04L | - | Common to OTTI(H91W,H92W). |
| EK WAGON | B11W | -20mm | S6 | DMI1020S06R | DMI1020S06L | - | Common to 2WD,4WD and DAYZ(B21W). |
| EK WAGON EK X | B33W,B36W B34W,B35W,B37W,B38W | -20mm | S36 | DMI1630S36R | DMI1630S36L | NPC001 | Common to 2WD,4WD and DAYZ(B4#W). Relocation of passenger seat pressure sensor is required. |
| EK X EV | B5AW | -20mm | S36 | DMI1631S36R | DMI1631S36L | NPC001 | Common to 2WD,4WD and SAKURA(B6AW). Relocation of passenger seat pressure sensor is required. |
| FTO | DE2A,DE3A | -10mm | S1 | DMI1040S01R | DMI1040S01L | - | |
| GALANT FORTIS | CY4A | -20mm | S6 | DMI1511S06R | DMI1511S06L | NPC001 | Offset toward door side is 7 mm. Interferes with shoulder width exceeding 610 mm. Common to LANCER EVO10(CZ4A) |
| GALANT FORTIS | CY4A | -30mm | SSD | DMI1521SSDR | DMI1521SSDL | NPC001 | Offset toward door side is 10 mm. Interferes with shoulder width exceeding 610 mm. Common to LANCER EVO10(CZ4A) |

| | 1 | | | | | | |
|-----------------------|------------------------|-------------------|-----------|----------------------------|-----------------|-----------|--|
| GALANT FORTIS | | | | | | | Offset toward door side is 7 mm. |
| SPORT BACK | CX4A | -20mm | S6 | DMI1512S06R | DMI1512S06L | NPC001 | Interferes with shoulder width exceeding 610 mm. |
| SPORT BACK | | | | | | | Common to LANCER EVO10(CZ4A) |
| | | | | | | | Offset toward door side is 10 mm. |
| GALANT FORTIS | CX4A | -30mm | SSD | DMI1522SSDR | DMI1522SSDL | NPC001 | Interferes with shoulder width exceeding 610 mm. |
| SPORT BACK | | | | | | | Common to LANCER EVO10(CZ4A) |
| GALANT,LEGNUM | EA,EC | -20mm | S1 | DMI1160S01R | DMI1160C011 | NDC001 | |
| GRANDIS | NA4W | -20mm | S4 | DMI1170S04R | | NPC001 | |
| GTO | Z15A,Z16A | -10mm | S1 | DMI1050S01R | | - | |
| 010 | 2137,2107 | 1011111 | 51 | DM11030301K | D/111030301E | | |
| | | | | | | | Offset toward door side is 8 mm. |
| i,i-MiEV | HA1W,HA3W,HA4W,HD4W | -10mm | S4 | DMI1060S04R | DMI1060S04L | _ | Interferes with shoulder width exceeding 545 mm. |
| , | , , , | | | | | | Interferes with Side support width exceeding 459 mm. |
| | | | | | | | Some seats require door dial removal. |
| | | | | | | | Lifting up behind the seat is not possible. |
| JEEP | J53~59 | -10mm | S1 | DMI1600S01R | DMI1600S01L | - | Floor drilling required. * |
| | | | | | | | * Right seat is on the rear console side, Left seat is on the rear left and right. |
| LANCER EVO7,8,9 | | | | | | | Tagine sout to on the roal solidore study determine the first time right. |
| LANCER EVO7,8,9 | CT9A,,CT9W,CS2A,CA5A | -20mm | S1 | DMI1490S01R | DMI1400C011 | _ | |
| | C19A,,C19W,C52A,CA5A | -20111111 | 51 | DM11490501R | DM11490501L | _ | |
| LANCER SEDIA WAGON | | | | | | | |
| LANCER EVO7,8,9 | | | | | | | |
| LANCER SEDIA | CT9A,CT9W | -40mm | SSD | DMI1480SSDR | DMI1480SSDL | - | |
| LANCER SEDIA WAGON | | | | | | | |
| | | | | | | | Offset toward door side is 7 mm. |
| LANCER EVO10 | CZ4A | -20mm | S6 | DMI1510S06R | DMI1510S06L | NPC001 | Interferes with shoulder width exceeding 610 mm. |
| | | | | | | | |
| LANCER EVO10 | CZ4A | -30mm | SSD | DMI1520SSDR | DMI152055DI | NDC001 | Offset toward door side is 10 mm. |
| LANCER EVOID | CZHA | 5011111 | 330 | DMITSZOSSBK | DM1132033DE | 141 0001 | Interferes with shoulder width exceeding 610 mm. |
| | | | | | | | Offset toward door side is 15 mm. |
| MINICAB,MINICAB-MiEV | U61,62V,U67,U68 | ±Omm | S1 | DMI1420S01R | | _ | Common to TOWN BOX(U61,U62),CLIPPER(U71V). |
| MINICAD, MINICAD-MIEV | 061,627,067,068 | ±0IIIII | 51 | DM11420501R | - | _ | |
| | | | | | | | 1-position offset seat rail. |
| MINICA | H20 | -30mm | S4 | DMI1330S04R | | - | Offset toward door side is 10 mm. |
| MINICA | H30,H31,H32 | -30mm | S4 | DMI1440S04R | | - | C TODDO DI(U424 U474) |
| MINICA | H42A,H42V,H47A,H47V | ±0mm | S4 | DMI1341S04R | | - NIDCOO! | Common to TOPPO BJ(H42A,H47A). |
| MIRAGE MIRAGE | A05A CM,CK,CJ,CD,CB | -25mm | S6 | DMI1450S06R DMI1461S01R | | NPC001 | |
| MIRAGE | CM,CK,CJ,CD,CB | -10mm -40mm | S1 SSD | DMI1461SUIR DMI1471SSDR | | - | |
| OUTLANDER | CW5W,GF7W,GF8W | -40IIIII -30mm | S36 | DMI147153DR DMI1090S36R | | | Common to RVR(GA3 '10.2~ GA4 '11.10~). |
| OUTLANDER PHEV | GG2W,GG3W | -30mm | S36 | DMI11090536R | | | COMMINGE TO TAKE TO THE TITLE OF |
| OUTLANDER PHEV | GG2W,GG3W | -20mm | LS9 | | DMI1110S30L | | |
| OUTLANDER PHEV | GN0W | -10mm | S36 | DMI1700S36R | | | Passenger seat is equipped with a surface pressure sensor for the seat belt warning lamp. |
| OO LEANDER FILE | 0.4044 | 1011111 | 550 | PI-1111 / 00220K | PI-111 / 00000C | 111 0002 | I assenger seat is equipped with a surface pressure sensor for the seat beit warning lamp. |

| PAJERO | L040,L140 | -20mm | S1 | DMI1370S01R | DMI1370S01L | - | The seat belt anchor is fixed to the floor. |
|-------------|------------|---------|-----|-------------|-------------|--------|--|
| PAJERO | V10~40,V55 | -25mm | S36 | DMI1350S36R | DMI1350S36L | - | Offset toward console side is 5 mm. |
| PAJERO | V60,V70 | -20mm | S4 | DMI1360S04R | DMI1360S04L | NPC001 | |
| PAJERO | V80,V90 | -20mm | S36 | DMI1380S36R | DMI1380S36L | NPC001 | |
| PAJERO IO | H60,H70 | -15mm | S4 | DMI1390S04R | DMI1390S04L | - | |
| PAJERO Jr. | H57A | -20mm | S4 | DMI1410S04R | DMI1410S04L | - | |
| PAJERO MINI | H56A | -20mm | S4 | DMI1411S04R | DMI1411S04L | - | |
| PAJERO MINI | H53A,H58A | -15mm | S4 | DMI1400S04R | DMI1400S04L | - | |
| ROSA | BE664 | No data | S1 | DMI1530S01R | DMI1530S01L | - | Mounting dimensions required. Micro bus (Handle center shifts by 30 mm or more) |
| RVR | N13W,N23W | -15mm | S4 | DMI1070S04R | DMI1070S04L | - | |
| RVR | N60W~N74W | -20mm | S16 | DMI1080S16R | DMI1080S16L | - | |
| RVR | GA3,GA4 | -30mm | S36 | DMI1091S36R | DMI1091S36L | NPC001 | Seat drop is from Model OUTLANDER(CW5W) specifications. |
| TOPPO | H82A | -20mm | S4 | DMI1011S04R | DMI1011S04L | - | |
| TOPPO BJ | H42A,H47A | -30mm | S4 | DMI1340S04R | DMI1340S04L | - | Common to MINICA(H42A,H42V,H47A,H47V). |
| TOWN BOX | U61,U62 | ±Omm | S1 | DMI1421S01R | - | - | Offset toward door side is 15 mm. Common to MINICAB(U61,U62),CLIPPER(U71V). 1-position offset seat rail. |