

The seat drop value described in the compatibility table is primarily a value relative to the original-equipment seat.

It is measured by mounting a Recaro Reclining seat.

— explanatory note — Differences may arise due to the position of the thickness and shape of the bottom of the seat, and seat settling due to aging of the original-equipment seat.

Note: If the original-equipment seat incorporates a height adjustment function, this value is relative to the lowest position.

Note: As a general rule, driver's seat data (passenger seats have different values depending on the presence or absence of height adjustment function)

SWEDEN

SAAB

Model Name	Model Code	Seat Drop	Type	Right Part No.	Left Part No.	Side SRS	Remarks
9-3	DB	-10mm	B1	ISA1010B01R	ISA1010B01L	NPC003	Seat drop is from Model OPEL VECTRA(Z02Z) specifications.

VOLVO

Model Name	Model Code	Seat Drop	Type	Right Part No.	Left Part No.	Side SRS	Remarks
240	AB230	-20mm	B4	IVO1010B04R	IVO1010B04L	-	Common to 164,260.
740	7B	-20mm	B1	IVO1032B01R	IVO1032B01L	-	Cannot be installed on vehicles equipped with SIPS. Seat drop is from Model 940(9B) specifications.
760	7B	-20mm	B1	IVO1033B01R	IVO1033B01L	-	Cannot be installed on vehicles equipped with SIPS.
850	8B	-15mm	B4	IVO1021B04R	IVO1021B04L	-	
940	9B	-20mm	B1	IVO1030B01R	IVO1030B01L	-	Cannot be installed on vehicles equipped with SIPS.
960	9B	-20mm	B1	IVO1031B01R	IVO1031B01L	-	Cannot be installed on vehicles equipped with SIPS.
S40,V40	4B	-30mm	B1	IVO1050B01R	IVO1050B01L	NPC001	
V40	MB,MD	-20mm	B6	IVO1040B06R	IVO1040B06L	NPC002	For wagons only. Relocation of the slide sensor is required. Common to S60,V60(FB4).
S60,V60	FB4	-20mm	B6	IVO1041B06R	IVO1041B06L	NPC002	Relocation of the slide sensor is required. Common to S40,V40(MB,MD).
S60	RB5	±0mm	B4	IVO1062B04R	IVO1062B04L	-	Cancellers cannot accommodate side airbags. Cancellers must be removed from the original-equipment seat and left on the floor.
S70,V70	8B	-15mm	B4	IVO1020B04R	IVO1020B04L	-	
S70,V70	SB5	±0mm	B4	IVO1060B04R	IVO1060B04L	-	Cancellers cannot accommodate side airbags. Cancellers must be removed from the original-equipment seat and left on the floor.
S80,V80	TB6	±0mm	B4	IVO1061B04R	IVO1061B04L	-	Cancellers cannot accommodate side airbags. Cancellers must be removed from the original-equipment seat and left on the floor.
XC60	DB	±0mm	B16	IVO1042B06R	IVO1042B06L	NPC001	Relocation of the Position memory is required. Seat drop is from Model XC70(BB) specifications.
XC70	BB	±0mm	B16	IVO1070B16R	IVO1070B16L	NPC001	Relocation of the Position memory is required.

XC90	CB	±0mm	B16	IVO1080B16R	IVO1080B16L	-	Cancellers cannot accommodate side airbags. Cancellers must be removed from the original-equipment seat and left on the floor. Relocation of the Position memory is required.
------	----	------	-----	-------------	-------------	---	--